



Technical Note

Installation Issue with BTW-CE and Dell Axim

Document # BTW-PROJ-TECHNOTES-030320-1030

March 20, 2003

Version 1.0



Dell Axim X5

WIDCOMM, Inc.

Wireless Internet and Data Communication
© Copyright 2000-2003. All rights reserved.
9645 Scranton Road, Suite 205
San Diego, CA 92121
Voice: (858) 453-8400 Fax: (858) 453-5735
Email : info@widcomm.com or support@widcomm.com

1 Problem when installing BTW-CE with BrainBoxes, Billionton, and CC&C Cards on Dell Axim.

1.1 DESCRIPTION OF PROBLEM

When installing BTW-CE 1.3.1.46 on Dell Axim the Brainboxes, Billionton, and CC&C cards are installed with the wrong COM port setting. After the installation has completed BTW-CE thinks no card is installed and is unable to start the Bluetooth stack.

1.2 SOLUTION

Re-install BTW-CE 1.3.1.46. The second installation of BTW-CE will correctly assign COM port 7 to the card. At this point the BTW-CE Bluetooth stack should initialize and startup.